






| | | g Glue" N | Means | | AirForce System |
|------|---------------|---------------------|----------------|------------------|-----------------|
| | | | | | |
| | | QUALI | TY LEVEL | | |
| "The | Achievable Ou | uality is just comp | oromises the c | ustomer has to a | ccept " |
| 1116 | | adinty to just some | nonnoco une e | | oocpt |
| | Price | Glue Line | Heat B | Moisture B | Water B |
| EVA | Price | Glue Line | Heat R. | Moisture R. | Water R. |































| AirForce System | | BIESSE AirForce System | | | |
|--|--------------------------|---------------------------|--|--|--|
| RETURN OF INV | ESTMENT | | | | |
| " The return of investment has to consider several factors " | | | | | |
| | PUR | AFS | | | |
| DARK/WHITE TAPE CHANGEOVER | 20 min/day | 2 min/day | | | |
| MAINTANANCE | 10 min/day | 1 min/day | | | |
| WARM UP TIME | 45 min/day | 3 min/day | | | |
| total | 75 min/day 25 h/month | 6 min/day 2 h/month | | | |
| | 300 h/year | 24 h/year | | | |

| |
|------|
| |

